HERITAGE-WTI, Inc.

1250 St. George Street East Liverpool, Ohio 43920-3400

Phone: 330-385-7337 Fax: 330-385-7813

Web Site: www.heritage-wti.com



February 3, 2010 VIA UPS

Mr. George Czerniak, Chief U.S. EPA Region V Air Enforcement and Compliance Assurance Branch Mail Code AE-17J 77 West Jackson Chicago, IL 60604

Ms. Pamela Korenewych OEPA-DAPC-NEDO Environmental Specialist 2110 E. Aurora Road Twinsburg, OH 44087

RE:

HERITAGE-WTI, INC.

EXCESSIVE EXCEEDANCE REPORTING

Dear Mr. Czerniak:

Please find enclosed a written report entitled MACT Excessive Exceedance Report for Heritage-WTI, Inc. This report is required by 40 CFR 63.1206 (c)(3)(vi) whenever there is more than ten emission standard or operating parameter exceedances that occur within a sixty-day period.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are certain penalties for submitting false information including the possibility of fine and imprisonment for knowing violations.

Thank you and if you have any questions or comments, please call me at the above number.

Sincerely,

John Peterka President

Heritage-WTI, Inc.

cc: Ed Fasco, Ohio EPA-DAPC-NEDO



MACT EXCESSIVE EXCEEDANCE REPORT

Heritage-WTI, Inc

February 3, 2010

Events

	<u>ents</u>				to the state of th		caan non con c	Note that the base is not a second	
#	Name	Start Time	End Time	Cause (report)	Cause Description	Corrective Actions	(hr)	(min)	(sec)
1	THC	12/3/2009 10:13:21 AM	10:25:22 AM	Error - Poor Operation	Operator fed waste at an inappropriate time.	Restarted unit. Reviewed operating guidance with operators.	0	12	1
2	THC	12/3/2009 10:33:24 AM	10:46:23 AM	Error - Poor Operation	Operator fed waste at an inappropriate time.	Restarted unit. Reviewed operating guidance with operators.	0	12	59
3	THC	12/7/2009 2:48:22 PM	2:55:23 PM	Error - Feed Prep	Poor feed prep caused THC event.	Remove slide gates on remaining containers.	0	7	1
	SCC Pressure Using Seals	12/7/2009 6:25:37 PM		Operator Error - Feed Prep	Poor feed prep caused THC event.	Drop ring on remaining containers.	0	0	6
5	SCC Pressure Using Seals	12/7/2009 6:25:46 PM		Operator Error - Feed Prep	Poor feed prep caused THC event.	Drop ring on remaining containers.	0	0	5
6	SCC Pressure Using Seals	12/8/2009 2:42:25 AM		Operator Error - Feed Prep	Improper charge size caused THC event.	Reduce charge size.	0	0	2
7	SCC Pressure Using Seals	12/21/2009 9:04:22 AM	a e	Operator Error- Feed Prep	Improperly prepared container feed caused THC spike.	Revised feed prep and restarted unit.	0	0	3
7	SCC Pressure Using Seals	12/21/2009 9:04:30 AM		Operator Error- Feed Prep	Improperly prepared container feed caused THC spike.	Revised feed prep and restarted unit.	0	0	3
8	THC	1/6/2010 9:04:25 PM			Improper line blowdown caused THC exceedance.	Reduce line blowdown. Restart unit.	0	51	58
9	RJ DP	1/14/2010 6:17:28 AM		Operator Error - Poor Operation	Operator failed to maintain a minimum ring jet differential pressure.	Increased RJ flow. Restarted unit.	0	7	1
10	SCC Pressure Using Seals	1/29/2010 4:44:48 PM		Operator Error - Feed Prep	Improperly prepared container feed caused THC spike.	Reduce charge size. Restart unit.	0	0	3
10	SCC Pressure Using Seals	1/29/2010 4:44:57 PM		Operator Error - Feed Prep	Same as prior event	Reduce charge size. Restart unit.	0	0	2

bcc:

Env. Dept Frank Murray Bob Buchheit Kevin Lloyd

file name: environ/MACT/HWC MACT/exceedances/eer10_0203